## REGULATORY REFORM (FIRE SAFETY) ORDER 2005 (Less than five employed).

NAME of COMPANY:	RESPONSIBLE PERSON:
ADDRESS (inc. postcode):	
DATE OF FIRE RISK ASSESSMENT:	Tel. no:
NAME OF PERSON CARRYING OUT THE FIRE RISK ASSESSMENT:	

## RECORD OF SIGNIFICANT FINDINGS.

## **ACTION PLAN FOR THE WORKPLACE:**

Priority A: High priority; immediate action required for legislative compliance

Priority B: Medium priority; action required for legislative compliance or responsible fire safety management

Priority C: Low priority; action required, considered good fire safety practice

	LOCATION	HAZARD	PERSONS WHO MAY BE HARMED	PRIORITY RISK RATING	ACTION/CONTROL MEASURES REQUIRED	ACTIONED BY/DATE
1	Whole of	Inadequate means of giving	Staff &		Provide a suitable fire alarm system to give early warning in case of	
	premises	warning in case of fire.	visitors	Α	fire. Any alarm system should include smoke detection devices be should be audible throughout the premises & comply with B.S. 5839	
2	Front building	Single staircase. Protected route of escape not	Staff & visitors		Ensure protection of this route; Remove combustible seats from first floor landing;	
		available from first & second floors.	VISITOIS	A	Remove combustible seats from first floor landing; Remove document/mail collection unit from first floor landing or alternatively provide wooden doors for each compartment which can be kept locked shut;	
3	Boiler Room (adjacent to small interview/mail room).	Louvre Doors	Staff & visitors	A	Replace Louvre doors with Fire Resisting doors which should be kept locked shut at all times. Ensure low level ventilation for boiler as required;	
4	Fire door to single staircase (Ground floor)	'Fire Door – Keep shut' notice missing	Staff & visitors	В	Supply & permanently fixed 'Fire Door-Keep Shut' signs on both faces of the door.	

Important: If in doubt seek professional advice.